

## LPF-C021303S


## 22.00 [0.866] — — 16.00 [0.630] <del>—</del> 5.08 [0.200] Ø2.80 [Ø0.110] (2 PLS.) 10.00 [0.394] 3.60 [0.142] (2 PLS.) - 5.80 [0.228] - 2.00 [0.079] 13.72 [0.540]


## NOTES:

- 1. THE END OF THE LIGHT PIPE IS DIFFUSED.
- 2. RECOMMENDED LED: SML-LX1206 SERIES, SINGLE COLOR SML-LX1210 SERIES, BICOLOR.
- 3. STACKABLE WITH LPF-CO21304S.
- 4. MATERIAL: CLEAR PC. 94V-0.









UNCONTROLLED DOCUMENT

\*UNILESS OTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XXX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MN= +DECINAL PRECISION ARE: X=±1 (±0.039), XXX=±0.5 (±0.020), XXX=±0.127 (±0.005).

REV.

PART NUMBER LPF-C021303S

DOUBLE UNIT, STACKABLE RIGHT ANGLE SMT LIGHT PIPE.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



GB

290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY:

CHECKED BY: APPROVED BY: DATE: PAGE:

8.7.02 1 OF 1 SCALE: N/A