

Precision Air-Core Tach/Speedo Driver with Return to Zero

CS8190

The CS8190 is specifically designed for use with air-core meter movements. The IC provides all the functions necessary for an analog tachometer or

CS8190



