

Issue Date: 10/09/2024  
Effective Date: 17/09/2024

MANAGEMENT SUMMARY

Pressure sensitive cover tape will be replaced by hot seal cover tape

CHANGE CATEGORY

[X] Design

DATASHEET UPDATE ART1K9FH

INFORMATION NOTIFICATION

THE CURRENT DATASHEET CONTAINS AN ERROR IN TABLE 10 (LIST OF COMPONENTS). VALUE OF CAPACITOR C3 IS MENTIONED AS 100PF. THIS SHOULD BE 43PF.  
THE UPDATED DATASHEET WILL CONTAIN THE CORRECT VALUE.

WHY DO WE ISSUE THIS INFORMATION NOTIFICATION  
TO NOTIFY CUSTOMERS ON THE UPDATE IN TABLE 10 OF THE DATASHEET.  
IDENTIFICATION OF AFFECTED PRODUCTS

Product identification does not change

IMPACT

DATA SHEET REVISION

A new datasheet will be issued

DISPOSITION OF OLD PRODUCTS

ADDITIONAL INFORMATION

Affected products, sales history information as well as self-qualification / additional documents can be accessed here: [view online](#)

## CONTACT AND SUPPORT

For all inquiries regarding the ePCN tool application or access issues, please contact [Ampleon "Quality Support Team"](#).  
For all Quality Notification content inquiries, please contact your local Ampleon Sales Support team.

At Ampleon we are dedicated to creating optimal value for our customers.  
Ampleon Quality Management Team.

## ABOUT AMPLEON

Created in 2015, Ampleon is shaped by 50 years of RF power leadership and is set to exploit the full potential of data and energy transfer in RF. Ampleon has more than 1,250 employees worldwide, dedicated to creating optimal value for customers. Its innovative, yet consistent portfolio offers products and solutions for a wide range of applications, such as cellular base stations, radio/TV/broadcasting, radar, air traffic control, cooking, lighting, industrial lasers and medical. For details on the leading global partner in RF Power, visit [www.ampleon.com](http://www.ampleon.com).